
## AUTOMATION COLLARS


THESE DETAILS ARE USED TO RETAIN AUTOMATION SHAFTING.
ONE COLLAR AT EACH END OF THE SHAFT, NEXT TO A
PILLOW BLOCK WILL RETAIN THE SHAFTING



| JOLICO NO. | OLD "J" NO. | REF. NO.     | REF. NO. | Α    | В    | С   | D      | Ε   |
|------------|-------------|--------------|----------|------|------|-----|--------|-----|
| J-55501    | J-55405     | DX18-28-1405 | AC-28    | 2.00 | 3.00 | .88 | 1/2-13 | .50 |
| J-55502    |             |              |          | 1.47 | 2.25 | .75 | 3/8-16 | .38 |

## PILLOW BLOCKS

THESE SELF LUBRICATION PILLOW BLOCKS ACT AS A BUSHING FOR AUTOMATION SHAFTING.



PAGE JH-26 12-2000